GFWMICBCBM4000
PROFESSIONAL BROADCAST/PODCAST MICROPHONE BOOM STAND
WITH ON-AIR INDICATOR LIGHT

Instruction Manual

GFWMICBM4000 offers two desk mounting options a desk clamp or desk insert.

Mounting with the Desk Clamp

1

Unscrew the clamp so that the opening is large enough to fit over the edge of your desk.

2

Push the clamp all the way onto the desk edge. Then, fasten the clamp to the desk by turning the knob tightening it in place.

3

Insert the arm into the hole at the top of the clamp. Then, insert and tighten the mic holder on the top of the boom.

Mounting with the Desk Insert

1

1" (25mm)

2.5"

0.6 - 2"
(15 - 50mm)

Use a 1" hole cutter and drill out a hole at least 2.5" from the edges of the desk.

2

Unscrew the nut from the desk insert and drop it into the hole. Screw the nut onto the desk insert from the underside until it is tight.

3

Insert the arm into the hole in the top of the desk insert.

Instruction Manual

USB Power

Plug the USB power supply to any device with a USB connector to power the GFWMICBCBM4000.

Power Switch

Increase Brightness

Change the Light Color

Turn On/Off LED Light

Decrease Brightness

Tension Adjustment Screw

To make fine-tune tension adjustments turn the screw left to decrease tension and turn right to increase tension.