

Blackbox™ User Guide

Portable USB 3.0 External Hard Drive



Proprietary Notice and Disclaimer


Unless noted otherwise, this document and the information herein disclosed are proprietary to Glyph Technologies, 3736 Kellogg Road, Cortland NY 13045 ("GLYPH"). Any person or entity to whom this document is furnished or having possession thereof, by acceptance, assumes custody thereof and agrees that the document is given in confidence and will not be copied or reproduced in whole or in part, nor used or revealed to any person in any manner except to meet the purposes for which it was delivered. Additional rights and obligations regarding this document and its contents may be defined by a separate written agreement with GLYPH, and if so, such separate written agreement shall be controlling.

The information in this document is subject to change without notice, and should not be construed as a commitment by GLYPH. Although GLYPH will make every effort to inform users of substantive errors, GLYPH disclaims all liability for any loss or damage resulting from the use of this manual or any software described herein, including without limitation contingent, special, or incidental liability.

© 2002-2019 Glyph Technologies. All rights reserved. Specifications are subject to change without notice. Glyph and the Glyph logo are registered trademarks of Glyph Technologies. All other brands and product names mentioned are trademarks of their respective holders.

BlackBox Overview

Physical Connections



Accessories

The following accessories are included with BlackBox:

USB 3.0 micro cable. Use this to connect BlackBox to any computer with a USB port. The cable provides both power and data connectivity for BlackBox.



Note: No power adapter is required to operate BlackBox.

Getting Started

Connect BlackBox to your computer

Use the included USB cable to connect BlackBox to your computer. BlackBox comes pre-formatted for Mac and is ready for use out of the box. If you plan to use BlackBox with Microsoft Windows, please follow the instructions at the bottom of this page. To use BlackBox with your computer, you need:

- A Mac or PC with a USB 2.0 or 3.0 port, and one of the following operating systems:
 - OS X version 10.5 or later
 - Windows 8, Windows 7, Windows Vista, or Windows XP with Service Pack 3 or later



WARNING: Always be sure to properly eject the drive from your desktop before physically unplugging BlackBox from your computer. You can accomplish this by either dragging the BlackBox icon to the trash in the dock or by selecting the BlackBox icon and pressing the “command” and “E” keys simultaneously.

Windows Formatting Instructions (7, Vista, XP, 2000)

1. Click the Start menu button (bottom left corner) and right-click My Computer and click Manage.
2. In the Computer Management window, under Storage, click Disk Management.
The Write Signature wizard pops up.
3. Use the wizard to write a signature to the new drive. If you want only one partition we suggest using a primary partition and selecting the maximum size. In most cases you’ll want to use NTFS volumes, this is the default for most versions of Windows. Choose FAT32 if you want to use the drives with Windows 98 or ME , or if you want to use the drive with Windows and Mac OS.
4. Formatting will take a few minutes, after which your drive will be ready to use.

Warranty & Technical Support

What is included in the BlackBox warranty?

Your purchase of BlackBox from an authorized Glyph reseller includes a comprehensive three-year warranty. Glyph warrants that your BlackBox purchase is free from material and mechanical defects. Proof of purchase may be required to receive warranty service. If you are unable to provide a valid proof of purchase, the warranty period will be calculated based on the original date of sale between Glyph and the authorized reseller.

What is not covered?

The BlackBox warranty does not cover damage or accidental damage caused by misuse, modification, alteration, tampering, an unsuitable operating environment, improper care, or failure caused by another product for which Glyph is not responsible.

What is the warranty procedure?

- 1) Contact Glyph and obtain an RMA (Return Merchandise Authorization) number.
- 2) Carefully pack and ship your BlackBox to the address provided by the Glyph service representative. There is no need to include cables of any kind, just the BlackBox unit. Be sure the box is clearly labeled with your RMA number in several places.

Contact Us

If at any time you have questions regarding BlackBox, please contact us using one of these methods:

Phone support 855.335.0345 (toll-free U.S. only)
607.275.0345 (international)

Email tech@glyphtech.com

Web www.glyphtech.com/support

NOTE: Before contacting Glyph support, we recommend you gather the following information about your configuration:

- BlackBox serial number (this is located on the bottom of your BlackBox)
- Operating System (Windows XP/7/8, Mac OS X 10.5, 10.6, 10.7 etc)